



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>DE/BVS/QAR07.0008/14</b>	Page 1 of 1
QAR Free Ref. No.:	<b>ZQS/E163/23</b>	Status: <b>Issued</b>
Details of change:	No changes.	Date of issue: <b>2023-05-12</b>
Location(s) audited:	<b>RECHNER Industrie-Elektronik GmbH</b> Gaußstrasse 6-10 68623 Lampertheim <b>Germany</b>	Valid until: <b>2026-06-03</b>  Audit date: <b>2023-04-18</b>
Issuing ExCB:	<b>BVS - DEKRA Testing and Certification GmbH</b>	
Manufacturer:	<b>RECHNER Industrie-Elektronik GmbH</b> Gaußstrasse 6-10 68623 Lampertheim	
Location of Manufacturer:	<b>Germany</b>	
Product information:	Sensors, proximity sensors and isolating switching amplifiers (Ex Barriers) Equipment for level detection, level control, level measurement.	
Type of protection:	<b>Intrinsic safety "i" Encapsulation "m" Protection by enclosure "t" Type of protection "n"</b>	
Related QARs:		
<a href="#">DE/BVS/QAR07.0008/00</a>	<a href="#">DE/BVS/QAR07.0008/01</a>	<a href="#">DE/BVS/QAR07.0008/02</a>
<a href="#">DE/BVS/QAR07.0008/03</a>	<a href="#">DE/BVS/QAR07.0008/04</a>	<a href="#">DE/BVS/QAR07.0008/05</a>
<a href="#">DE/BVS/QAR07.0008/06</a>	<a href="#">DE/BVS/QAR07.0008/07</a>	<a href="#">DE/BVS/QAR07.0008/08</a>
<a href="#">DE/BVS/QAR07.0008/09</a>	<a href="#">DE/BVS/QAR07.0008/10</a>	<a href="#">DE/BVS/QAR07.0008/11</a>
<a href="#">DE/BVS/QAR07.0008/12</a>	<a href="#">DE/BVS/QAR07.0008/13</a>	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
<a href="#">IECEX BVS 07.0015 issue: 0</a>	<a href="#">IECEX BVS 07.0015 issue: 1</a>	<a href="#">IECEX BVS 07.0015 issue: 2</a>
<a href="#">IECEX BVS 07.0031 issue: 0</a>	<a href="#">IECEX BVS 07.0031 issue: 1</a>	<a href="#">IECEX BVS 07.0031 issue: 2</a>
<a href="#">IECEX BVS 07.0031 issue: 3</a>	<a href="#">IECEX BVS 07.0031X issue: 4</a>	<a href="#">IECEX BVS 07.0032 issue: 0</a>
<a href="#">IECEX BVS 07.0032 issue: 1</a>	<a href="#">IECEX BVS 10.0087X issue: 0</a>	<a href="#">IECEX BVS 10.0087X issue: 1</a>
<a href="#">IECEX BVS 10.0088X issue: 0</a>	<a href="#">IECEX BVS 10.0088X issue: 1</a>	<a href="#">IECEX BVS 17.0088X issue: 0</a>
<a href="#">IECEX CSA 21.0011X issue: 0</a>		

Comments: